

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 1 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Delete the title page and substitute therefor the attached title page.

In the drawings, sheet 1, Fig. 2, reference numeral "22" on the sidewall of outwardly extending flange 24 should be deleted and reference numeral --27-- should be applied to the stamped portion;

In the drawings, sheet 1, Fig. 2, reference numeral --43-- should be applied to the left-hand side hub of the paper roll holder assembly 40; reference numeral --58-- should be applied to the rear wall of the chassis 55; reference numeral --57-- should be applied to the left-hand side spaced parallel side wall of chassis 55; reference numeral --38-- should be applied to the clip extending from the rear wall 32 of the housing 21.

In the drawings, sheet 1, Fig. 2, reference numeral --121-- should be applied to the drive roller segments of the drive roller 120.

In the drawings, sheet 1, Fig. 2, reference numeral --105-- should be applied to the transfer roller assembly; reference numeral --106-- should be applied to the shaft 106 of the transfer roller assembly 105; reference numeral --110-- should be applied to the transfer mechanism; reference numeral --112-- should be applied to the indented or removed portion of the cylindrical portion 111 of the shaft 106; reference numeral --115-- should be applied to the snap clip which receives the indented or removed portion 112 of the cylindrical portion 111 of the shaft 106.

**United States Patent [19]**

LaCount et al.

[11] Patent Number: **6,032,898**[45] Date of Patent: **Mar. 7, 2000****[54] MULTIPLE ROLL TOWEL DISPENSER**

[75] Inventors: Kenneth H. LaCount, Pulaski; Diane L. Stephan, Green Bay; Todd G. Welsch, Green Bay; Alan J. Pierquet, Green Bay; Alvin P. Paul, Green Bay, all of Wis.

[73] Assignee: Alwin Manufacturing Co., Green Bay, Wis.

[21] Appl. No.: 08/705,326

[22] Filed: Aug. 29, 1996

[51] Int. Cl.<sup>7</sup> ..... A47K 10/38; B26F 3/02;  
B65H 35/04

[52] U.S. Cl. ..... 242/564.2; 242/564.4;  
225/16; 225/34

[58] Field of Search ..... 242/564.4, 564.2;  
226/127, 128, 129; 225/10, 11, 12, 14,  
15, 16, 34, 39, 43, 46, 42, 47; 83/649,  
650

**[56] References Cited****U.S. PATENT DOCUMENTS**

2,149,088	2/1939	Gruenwald	.....	225/16 X
2,919,842	1/1960	Ballas	.	
2,930,664	3/1960	Liebisch	.	
2,974,839	3/1961	Ballas et al.	.	
3,007,650	11/1961	Burton	.	
3,126,234	3/1964	Ballas et al.	.	
3,288,387	11/1966	Craven, Jr.	.	
3,466,963	9/1969	Palson et al.	.....	225/16 X
3,628,743	12/1971	Bastian	.	
3,843,218	10/1974	Knueger et al.	.	
3,917,191	11/1975	Graham, Jr.	.	
4,067,509	1/1978	Graham, Jr.	.	
4,086,633	5/1978	Austin, Jr.	.....	226/129 X
4,165,138	8/1979	Hedge et al.	.	
4,192,442	3/1980	Bastian et al.	.	
4,203,562	5/1980	DeLucia et al.	.	
4,236,679	12/1980	Jespersen	.	

4,317,547	3/1982	Graham, Jr.	.
4,358,169	11/1982	Filipowicz	.
4,378,912	4/1983	Perrin et al.	.
4,396,163	8/1983	Graham, Jr.	.
4,403,748	9/1983	Cornell	.
4,406,421	9/1983	Schultz et al.	.
4,611,768	9/1986	Voss et al.	.
4,756,485	7/1988	Bastian et al.	.
4,846,412	7/1989	Morand	.
4,856,724	8/1989	Jespersen	.
5,125,548	6/1992	Perrin et al.	..... 225/16 X
5,294,192	3/1994	Omdoll et al.	.
5,400,982	3/1995	Collins	.
5,526,973	6/1996	Boone et al.	.

**FOREIGN PATENT DOCUMENTS**


2060799 8/1992 Canada ..... 242/564.4

Primary Examiner—Eugenia Jones  
Attorney, Agent, or Firm—Emrich & Dithmar

**[57] ABSTRACT**

A dispenser for dispensing a web from a roll of paper includes a housing and a cover connected thereto to provide access to the housing interior. The dispenser has mechanism for supporting a paper roll and a drive roller and tension roller operatively associated therewith which urges paper from the paper roll into contact with the drive roller for dispensing a length of paper from the paper roll. Actuator mechanism operates the drive roller and extends across substantially the entire housing at the bottom thereof. A roller frame assembly is mounted within the housing and carries the tension roller and a transfer roller. The transfer roller releasably holds the free end of a first paper roll while paper from the second roll is dispensed upon actuation of the actuator to rotate the drive roller. Because the paper from a second paper roll is positioned between the drive roller and the transfer roller, rotation of the transfer roller during rotation of the drive roller is prevented until the second paper roll is exhausted.

5 Claims, 5 Drawing Sheets




UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 3 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:




UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 4 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings, sheet 3, Fig. 6, the reference numeral "50" (not the reference numeral "50" pointing to the cover) should be deleted and reference numeral --51-- should be applied to the front panel of the cover 50.




UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 5 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings, sheet 4, Fig. 10, the reference numeral "131" pointing to the free end of the flight of paper 131 should be deleted and the reference numeral --132-- should be applied to the free end of the flight of paper 131.



UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 6 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings, sheet 5, Fig. 11, reference numeral --105-- should be applied to the transfer roller assembly; reference numeral --107-- should be applied to the journal on the right-hand end of the transfer roller assembly 105; reference numeral --108-- should be applied to the journal on the left-hand end of the transfer roller assembly 105; reference numeral --109-- should be applied to the stop plate on journal 108; and reference numeral --110-- should be applied to the transfer mechanism positioned generally centrally of the shaft of the transfer roller assembly 105.

In the drawings, sheet 5, Fig. 12, reference numeral --105-- should be applied to the transfer roller assembly; reference numeral --106-- should be applied to the shaft of the transfer roller assembly 105; reference numeral --107-- should be applied to the journal on the right-hand end of the transfer roller assembly 105; reference numeral --108-- should be applied to the journal on the left-hand end of the transfer roller assembly 105; reference numeral --110-- should be applied to the transfer mechanism positioned generally centrally on the shaft 106; and reference numeral --111-- should be applied to cylindrical portion of the shaft 106.

In the drawings, sheet 5, Fig. 13, reference numeral --105-- should be applied to the transfer roller assembly; and reference numeral --106-- should be applied to the shaft of the transfer roller assembly.

In the drawings, sheet 5, Fig. 14, reference numeral --105-- should be applied to the transfer roller assembly; reference numeral --106-- should be applied to the shaft of the transfer roller assembly 105; reference numeral --110-- should be applied to the transfer mechanism positioned generally centrally of the shaft 106; and reference numeral --112-- should be applied to the indented or removed portion of the cylindrical portion 111 of the shaft 106.

In the drawings, sheet 5, Fig. 15, reference numeral --105-- should be applied to the transfer roller assembly; and reference numeral --116-- should be applied to the groove or receptacle of the cylindrical portion 111 of the shaft 106.


In the drawings, sheet 5, Fig. 16, reference numeral --95-- should be applied to the tear bar; reference numeral --95a-- should be applied to the tabs of the tear bar 95; reference numeral --95b-- should be applied to the clips of the tear bar 95; reference numeral --95c-- should be applied to the serrated edge of the tear bar 95; and section line --17—17-- should be added at the middle portion of the drawing at the top and bottom thereof.

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 7 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:



In column 3, line 54, delete "44" and insert --22--.

In column 4, line 37, delete "121".

In column 6, line 34, delete "roller" and insert --roller segments--.

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,032,898  
APPLICATION NO. : 08/705326  
DATED : March 7, 2000  
INVENTOR(S) : LaCount et al.

Page 8 of 8

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 6, line 51, after "inserted" insert --under--.

In column 6, line 58, delete "rollers" and insert --roller segments--.

In column 6, line 65, delete "121" and insert --21--.

In column 8, claim 1, line 28, after "mounted on said housing" insert --,--.

In column 8, claim 1, line 32, delete "operating" and insert --operates--.

In column 8, claim 4, line 48, delete "complimentary" and insert --complementary--.

This certificate supersedes the Certificate of Correction issued February 17, 2009.

Signed and Sealed this  
Seventeenth Day of March, 2009



JOHN DOLL  
*Acting Director of the United States Patent and Trademark Office*